| Ref # | Hits | Search Query | DBs | Default Operator | Plurals | Time Stamp |
|----------|--------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------|---------------------|---------|------------------|
| L1 | 293 | 29/889.ccls. | US-PGPUB; USPAT; EPO; JPO; DERWENT | OR | ON | 2006/02/06 11:38 |
| L3 | 587165 | turbine or blisk or vane or (turbo adj machine) or compressor or (blade near2 disk) | US-PGPUB; USPAT; EPO; JPO; DERWENT | OR | ON | 2006/02/06 11:39 |
| L4 | 8740 | l3 and ("29".clas. or "228".clas. or "219".clas.) | US-PGPUB; USPAT; EPO; JPO; DERWENT | OR | ON | 2006/02/06 11:39 |
| L5 | 5506 | l4 and "29".clas. | US-PGPUB; USPAT; EPO; JPO; DERWENT | OR | ON | 2006/02/06 11:39 |
| L6 | 3563 | I4 and ((hole or gap or groove or space or trench or crack or open\$3) with (fill\$3 or plug\$3 or block\$3 or insert\$3 or fix\$3 or repair\$3 or mend\$3)) | US-PGPUB; USPAT; EPO; JPO; DERWENT | OR | ON | 2006/02/06 12:02 |
| L7 | 2563 | I6 and (solder\$3 or weld\$3 or bond\$3 or join\$3 or (laser near2 weld\$3) or (electron near3 weld\$3)) | US-PGPUB; USPAT; EPO; JPO; DERWENT | OR | ON | 2006/02/06 12:03 |
| L8 | 47 | I7 and ((hole or gap or groove or space or trench or crack or open\$3) near3 spacer) | US-PGPUB; USPAT; EPO; JPO; DERWENT | OR | ON | 2006/02/06 12:04 |
| L9 | 2278 | I4 and ((hole or gap or groove or space or trench or crack or open\$3) with (fill\$3 or plug\$3 or fix\$3 or repair\$3)) | US-PGPUB; USPAT; EPO; JPO; DERWENT | OR | ON | 2006/02/06 12:03 |
| L10 | 1721 | I9 and (solder\$3 or weld\$3 or bond\$3 or join\$3) | US-PGPUB; USPAT; EPO; JPO; DERWENT | OR | ON | 2006/02/06 12:03 |
| L11 | 25 | l10 and ((hole or gap or groove or crack or open\$3) near3 spacer) | US-PGPUB; USPAT; EPO; JPO; DERWENT | OR | ON | 2006/02/06 12:04 |
| L12 | 0 | l11 not l8 | US-PGPUB; USPAT; EPO; JPO; DERWENT | OR | ON | 2006/02/06 12:04 |
| L14 | 3380 | I5 and (solder\$3 or weld\$3 or bond\$3 or join\$3 or braz\$3) | US-PGPUB; USPAT; EPO; JPO; DERWENT | OR | ON | 2006/02/06 12:06 |

| L15 | 399 | l14 and ((hole or gap or crack) near5 (fill\$3 or plug\$3 or fix\$3 or repair43)) | US-PGPUB; USPAT; EPO; JPO; DERWENT | OR | ON | 2006/02/06 12:07 |
|-----|-----|-----------------------------------------------------------------------------------------|---------------------------------------------|----|----|------------------|
| L16 | 390 | 115 not 18 | US-PGPUB; USPAT; EPO; JPO; DERWENT | OR | ON | 2006/02/06 12:07 |